

<b>Event name :</b>	從高雄氣爆看香港管綫管理 記者招待會
<b>Event code :</b>	E008-HKIUS-Y14
<b>Event Date :</b>	9 <sup>th</sup> August 2014, 14:30 – 16:00

<b>Venue :</b>	香港管綫專業學會 會址
<b>Organizer :</b>	香港管綫專業學會
<b>Speakers :</b>	香港管綫專業學會 會長及前會長
<b>Program highlights :</b>	<p>There was a serious explosions caused by a gas leak in Kaohsiung happended on 3<sup>th</sup> to 5<sup>th</sup> August 2014. Our president, Ir Dr. King Wong was invited for an on-site investigation and technical exchange by the Kaohsiung Government.</p> <p>After his site-visit, a press conference had been held to cover the following issues:</p> <ol style="list-style-type: none"> <li>1. What caused the explosions in Kaohsiung</li> <li>2. How's the recovery status in this event</li> <li>3. The underground utility management system in Hong Kong</li> <li>4. Suggestions from HKIUS</li> </ol>
<b>References</b>	<p>Event details  <a href="http://www.hkius.org.hk/events-2014.html">http://www.hkius.org.hk/events-2014.html</a></p> <p>News clipping :  <a href="http://www.hkius.org.hk/news--video.html">http://www.hkius.org.hk/news--video.html</a></p>

<b>Event name :</b>	從高雄氣爆看香港管綫管理 記者招待會
<b>Event code :</b>	E008-HKIUS-Y14
<b>Event Date :</b>	9 <sup>th</sup> August 2014, 14:30 – 16:00

**Event Photos 活動相片**



**Introduction**



**Introduction**



**Importance of underground utilities**



**Demonstration of equipment  
How to prevent accident**



**Reporters were making important notes**